

# UNIVERSITY OF CALCUTTA



**SENATE HOUSE**

87/1, College Street

Kolkata-700 073, West Bengal, India.

Phone: 2241-0071 (6 lines), 2241-4984 (7 lines)

Email: malayh@rediffmail.com

## CORRIGENDUM

### Corrigendum for the NIT AR/07-07/2015 DATED 17/07/2015

DATA for the below mentioned Serial No.s in the BOQ FOR LAN, Wi-Fi connectivity may be read as mentioned below.

BOQ FOR LAN , Wi-Fi connectivity					
Sr. No.	DATA	MAKE	UNIT	UNIT RATE	AMOUNT
6	24 Port Ethernet 10/100/1000 Mbps managed switch with 2 (SFP) Port (WS-2960X-24TS-LL) with 3 yrs. warranty				
	Supply	CISCO	Nos.		
	Labour		Nos.		
7	28 Port Ethernet Gigabit PoE+ managed switch with 2 SFP ports (SG300-28PP-K9-NA) with 3 yrs. warranty				
	Supply	CISCO	Nos.		
	Labour		Nos.		
8	AIR-CT5520-K9 CISCO wireless controller Optimized to enable 802.11ac Wave 2 next-generation networks. Licenses to manage 50 AP should be installed from Day-1. The device should come with necessary mounting kits with 3 yrs. warranty.				
	Supply	CISCO			
	Labour				
9	AIR-CAP7021-D-K9 Dual-Band controller-based 802.11a/g/n (Indoor). The device should come with necessary mounting kits with DHCP Facilities, with 3 yrs. warranty.				
	Supply	CISCO			
	Labour				
10	AIR-CAP1532E-D-K9 802.11n Outdoor AP Ext Ant; D Reg Domain. The access point should come with lightning arrestors, mounting brackets. It should come with 4dBi/ 7 dBi gain omni directional antenna for frequency band 2.4/5 Ghz. with 3 yrs. warranty.				
	Supply	CISCO	Nos.		
	Labour				